

TREX 300 Spirit2

FW 3.0 (no changes to heli nor settings after upgrade from 2.8)




Unit spirit2 mounted //
with rotor blades




Geolink mounted horizontally on boom parallel with rotor blades and parallel with boom



State after initialisation in bank 1
Rotor is not spinning




State after spoolup in bank 0 (no stabilisation) rotor spools up




State at take-off in bank 1 (coax)

State when flying AND rescue
(bank 2): swash moved up but
stayed parallel to rotor blades





State with main axis vertical,
bank 1



How I proceed

- All these pictures are with motor disconnected, heli standing still, but I go through all the states as if I were taking off and flying.
- I use three banks with different settings (see next slide)
- My procedure is
 - connect battery in bank 1 (stabilisation = coax) but throttle is off, this also my mode for autoland
 - spool-up in bank 0 (stabilisation = OFF) throttle = 60%, wait for stable RPM
 - switch to bank 1 (stabilisation = coax) and fly
 - land in bank 1 (coax) and cut throttl

Bank settings

Bank Comparison			
	Bank 0	Bank 1	Bank 2
Sensor → Cyclic Gain	55%	60%	55%
Stabi → Function	Disabled	Coaxial	Rescue (Normal)
Stabi → Rescue collective pitch	60%	60%	80%
Stabi → Sticks priority	6	10	10
Stabi → Direction control rate	1	0	1

Swash positions

- After initialisation (bank 1) swash is very little nose down
- At spool-up (bank 0) swash is perfectly // with rotor blades
- At take-off (bank 1) swash is still perfectly // with rotor blades
- When in rescue (bank 2) swash moves up all the way but remains // with rotor blades
- When in flying mode (bank 1) and holding the heli with the main axis vertically, swash inclines nose down

conclusion

- The correct mounting requires the unit to be parallel to rotor blades
- Because of skids, the heli is inclined by approx. 5° nose down when spooling up and at take off. Swash is then // to rotor blades
- When hovering with main axis vertical, swach is inclined nose down (due to stabilisation / coax). This requires constant correction from the pilot
- With fw 2.8 some almost no correction was needed to hover in place. With fw 3.0 strong correction is needed (roll to the right, nick to aft)
- With fw 3.0 at landing the heli tipped to the right and rotor touched ground

