
































Unit version: 3.5.0
Unit uptime: 04:50
Log generated: 19:27:31
sab ago 26 2023

Flight Log - previous flight

00:00		Calibration Finished
00:10		Good Health Message
00:20		Good Health Message
00:30		Good Health Message
00:40		Good Health Message
00:50		Good Health Message
01:00		Governor was Engaged
01:10		Good Health Message
01:20		Good Health Message
01:30		Good Health Message
01:40		Good Health Message
01:50		Good Health Message
02:00		Good Health Message
02:10		Good Health Message
02:20		Good Health Message
02:30		Good Health Message
02:40		Good Health Message
02:50		Good Health Message
03:00		Good Health Message
03:10		Good Health Message
03:20		Good Health Message
03:30		Good Health Message
03:40		Good Health Message
03:50		Good Health Message
04:00		Good Health Message
04:10		Good Health Message
04:20		GeoLink connection is broken
04:30		GeoLink connection is broken
04:40		Power Voltage is low